

Baker

Evaluation of the **Baker Municipal Airport** yielded the following PCI values.

Section	Critical PCI	Surveyed PCIs				Predicted PCIs	
		1988	1991	1994	1997	2002	2007
A-2A	55			XX	93	74	56
A-3A	55				100	69	58
A-5	55				100	77	58
A-6	50				100	85	72
R-1	55			96	70	62	52
T-1	55			98	66	59	44
T-2	55			97	74	65	56
T-3	55			94	66	59	44
T-4	55				100	79	66

Pavement Condition Index (PCI) to **Pavement Condition Rating** conversion:

0 ≤ **Failed** ≤ 10 < **Very Poor** ≤ 25 < **Poor** ≤ 40 < **Fair** ≤ 55 < **Good** ≤ 70 < **Very Good** ≤ 85 < **Excellent** ≤ 100

"XX" in PCI columns indicates previous PCI values have been voided to account for new construction.

No entry in PCI columns indicates no inspection of the pavement section for the year.

PCI predictions are based on the assumption that current maintenance practices will continue with no major reconstruction.

All your pavements are in "good" or better condition. Taxiways T-1 and T-3 would benefit from routing and crack sealing within the next 5 years.